


MONTHLY PROGRESS PHOTOS July-2021



Epoxy Works (Basement B2)



MONTHLY PROGRESS PHOTOS July-2021



Pumps Room (Basement B1)



MONTHLY PROGRESS PHOTOS July-2021



Glass Partition at Lift Lobby
(Basement B1)



MONTHLY PROGRESS PHOTOS July-2021



First Fix False Ceiling (Entrances)




MONTHLY PROGRESS PHOTOS July-2021





**Insulation Works For HVAC / First Fix
False Ceiling (Ground Floor)**



MONTHLY PROGRESS PHOTOS July-2021




Insulation Works For HVAC (First Floor)



MONTHLY PROGRESS PHOTOS July-2021



First Fix False Ceiling For Wet Areas
(First Floor)



MONTHLY PROGRESS PHOTOS July-2021



First Fix False Ceiling For Wet Areas
(Second Floor)





2nd. Basement



Internal Ramp







1st. Basement



Ground Floor





Second Floor



Third Floor



Roof Floor

MONTHLY PROGRESS PHOTOS Aug-2021



Panels / Equipment rooms (B1)



MONTHLY PROGRESS PHOTOS Aug-2021



Final Coat Epoxy (Basements)



MONTHLY PROGRESS PHOTOS Aug-2021



Flooring For Lift Lobbies (Basements)



MONTHLY PROGRESS PHOTOS Aug-2021



Lift Lobbies Area (Ground Floor)



MONTHLY PROGRESS PHOTOS Aug-2021



False Ceilling at Corridor (Ground Floor)



MONTHLY PROGRESS PHOTOS Aug-2021



False Ceiling at Corridor (First Floor)



MONTHLY PROGRESS PHOTOS Aug-2021



HVAC Insulation (Second Floor)



MONTHLY PROGRESS PHOTOS Aug-2021



HVAC Insulation (Second Floor)

